

Tracker Week


Currents - Noise - Irrad.

(more in the sensor & mod. const meeting)

F. Hartmann
Th. Weiler, A. Furgeri

Please remember all, non-standard tests were done during the high throughput QTC phase
→ Statistics could/should be better!


I V with 2nd kink!




- Mostly localized on a small number of strips
 - LOCAL defect (difficult to predict)
 - Often accompanied by scratches or process defects.
 - Sensitive to:
 - RH
 - Vacuum - mechanic deformation!
 - Time under bias
 - ...
 - not to Temp.
- One can "play" with it!

In my personal opinion this is dangerous and difficult to predict wrt Noise/current!


Repeatability of leaky strips (an example)




Batch 16160 (S35)



Batch 18133 (S39)




Batch 27324 (S43)



NB. ST finds quite often a short at strip 104/105 (W6A)
ST quotes some leaky strips as bad Rpoly



I V with different vacuum levels



Preliminary!
Not observed on all sensors.


Sensor bow $\sim 50\mu\text{m}$ \rightarrow vacuum will impose slight mechanical deformation!
What is the level of mechanical stress in the final experiment?

Leakage currents vs. vacuum




ST production week 30 W5B
30211033013222

**No visual damage observed
On the critical strips!!!**






Some defects

possibly leading to high current/noise




There's no absolute correlation of current and visible defects


Scratches '03





Still long scratches!



Due to #leaky strips/sensor
9,9,7,9,6,4
At the same positions!
→ Complete batch rejected!




Worry: no visual defect seen!



- Latest available batches in KA!
- **Small statistics! (7)**
- Sensors from Set KA-S53,54,55,60
- No vacuum dependence observed!
- Still some leaky strips!
- **Still 2nd kink**


STM:
All processes frozen WEEK 32!
Add. passivation layer WEEK 39

Good batches!





No kink, very low currents!


Strip current vs. T of a dubious/failed strips



Strip after irradi. (on sensor)





Critical strip before irradi.
Does not show after irradi.



After irradi. ~10Y OB (more in the module construction)






Preliminary result of a defective module irradi. (thanks to FNAL/UCSB)



More measurements after irradi with cosmics & betas will follow, especially on the "defect" regions.

Noise before/after irradiad


preliminary (not fully annealed)






As expected the things are "better"
at least not worse after irrad.
(type inversion → lower field on junction
Effect shifted to higher voltages
→ Implications on the voltage vs. operation
→ Lorentzangle
→ More measurements to come!!



Strip currents on module



Some pictures of the module



Tests ongoing

- Assembly of 2 modules with particularly “bad” sensors
- Strips@ 1nA, 50nA, 300nA, 1 μ A, x μ A
- Parallel noise & strip current measurement to have a absolute correlation
(unfortunately with low statistics)
Modules were assembled & bonded yesterday, under measurement right now (hybrids arrived last friday).

“MY” Conclusions

- There are NO conclusions but the fact that sensors with a 2nd kink are difficult to predict wrt noise & currents.
- They are often sensitive to
 - RH
 - Possibly mechanical stress
 - Vbias
- They often come with visual defects!
- The effect is mostly **localized** with different sources.
- The effect lessens after irradi. or at least does not worsen.
- On a statistic of one the noise behave properly with T

**Due to the huge number of sensors (& modules to come)
it will be more and more difficult to investigate these problems!**
Possibly we are just one week before the final perfect
sensor production! There are good & bad batches!